

Report of Thorough Examination of Lifting Equipment

In accordance with the Lifting Operations and Lifting Equipment Regulations 1998

TEAM LIFTING SERVICES LIMITED SUITE 2039, 6-8, REVENGE ROAD, LORDSWOOD, KENT, ME5 8UD

Report No: TLS/JMCH/290325Q

Date of the Report: 29/03/2025

Report of a Thorough Examination of Lifting Equipment

In accordance with the Lifting Operations and Lifting Equipment Regulation 1998

Name and Address of owner of equipment:
J&M CRANE & TRANSPORT LTD
DENTON WHARF, MARK LANE,
GRAVESEND, KENT,
DA11 20D

Location of Equipment:
DENTON WHARF, MARK LANE,
GRAVESEND,
KENT,
DA11 20D

Sub Location of Equipment:

LC14JMC

Page:

DA11 2QD		D	DA11 2QD				1 01 2			
Qty	Serial Number Asset Number	Particulars sufficient to identify the equipment	Date of previous examination	Specify any Tests Applied	Date of this examination	SWL	Examination Frequency (Months) 6, 12, etc.	Latest date for next examination	Defects Y or N	
1	9048E	2 LEG CHAIN SLING – 6M	29/09/2024	None	29/03/2025	4.25t	6M	29/09/2025	N	
1	13.1.S3	DROP CHAIN – 1M	29/09/2024	None	29/03/2025	5.3t	6M	29/09/2025	N	
1	235393586	WEBBING SLING – 6M	29/09/2024	None	29/03/2025	3t	6M	29/09/2025	N	
1	082321250	WEBBING SLING – 6M	29/09/2024	None	29/03/2025	3t	6M	29/09/2025	N	
1	022316093	WEBBING SLING – 6M	29/09/2024	None	29/03/2025	3t	6M	29/09/2025	N	
1	22114960	WEBBING SLING – 6M	29/09/2024	None	29/03/2025	3t	6M	29/09/2025	N	
1	141214082	ROUND SLING – 1M EWL	29/09/2024	None	29/03/2025	3t	6M	29/09/2025	N	
1	141214086	ROUND SLING – 1M EWL	29/09/2024	None	29/03/2025	3t	6M	29/09/2025	N	
1	97	ALLOY BOW SHACKLE	29/09/2024	None	29/03/2025	8.5t	6M	29/09/2025	N	
1	98	ALLOY BOW SHACKLE	29/09/2024	None	29/03/2025	8.5t	6M	29/09/2025	N	
1	99	ALLOY BOW SHACKLE	29/09/2024	None	29/03/2025	8.5t	6M	29/09/2025	N	
1	LC14A	ALLOY BOW SHACKLE	29/09/2024	None	29/03/2025	8.5t	6M	29/09/2025	N	
1	4884D	ALLOY BOW SHACKLE	29/09/2024	None	29/03/2025	8.5t	6M	29/09/2025	N	
1	4884C	ALLOY BOW SHACKLE	29/09/2024	None	29/03/2025	8.5t	6M	29/09/2025	N	
1	LC14D	ALLOY BOW SHACKLE	29/09/2024	None	29/03/2025	8.5t	6M	29/09/2025	N	
1	801	ALLOY BOW SHACKLE	29/09/2024	None	29/03/2025	6.5t	6M	29/09/2025	N	

Examination Frequency; - 6M = 6 Months, 12M = 12 Months, SC = Written Examination Scheme, EX = After Exceptional Circumstances.



Report of Thorough Examination of Lifting Equipment

In accordance with the Lifting Operations and Lifting
Equipment Regulations 1998

TEAM LIFTING SERVICES LIMITED SUITE 2039, 6-8, REVENGE ROAD, LORDSWOOD, KENT, ME5 8UD

Report No: TLS/JMCH/290325Q

Date of the Report: 29/03/2025

Report of a Thorough Examination of Lifting Equipment

In accordance with the Lifting Operations and Lifting Equipment Regulation 1998

Name and Address of owner of equipment:	Location of Equipment:	Sub Location of Equipment:
J&M CRANE & TRANSPORT LTD	DENTON WHARF, MARK LANE,	LC14JMC
DENTON WHARF, MARK LANE,	GRAVESEND,	
GRAVESEND, KENT,	KENT,	Page:
DA11 2QD	DA11 2QD	2 of 2

Qty	Serial Number Asset Number	Particulars sufficient to identify the equipment	Date of previous examination	Specify any Tests Applied	Date of this examination	SWL	Examination Frequency (Months) 6, 12, etc.	Latest date for next examination	Defects Y or N
1	4399A	ALLOY BOW SHACKLE	29/09/2024	None	29/03/2025	3.25t	6M	29/09/2025	N
1	4399C	ALLOY BOW SHACKLE	29/09/2024	None	29/03/2025	3.25t	6M	29/09/2025	N
1	4429B	ENDLESS WIRE BOND	29/09/2024	None	29/03/2025	1t	6M	29/09/2025	N
1	20-4298320	FALL ARREST BLOCK – 10M	29/09/2024	Function	29/03/2025	136kg	6M	29/09/2025	N

Guidance Notes - Tests Applied: - None, Functional, Actual load applied, Dye Pen, MPI, PAT, etc Examination Frequency; - 6M = 6 Months, 12M = 12 Months, SC = Written Examination Scheme, EX = After Exceptional Circumstances.

Report of a thorough examination for equipment: -	1 st Report	Correctly	Repaired	Re-	*	
	Issued	Installed		Certified		

Declaration: - The equipment listed above is free from any defects and is safe to use.

Authenticating Signature:

Date: 29/03/2025

Authenticators Name: Damian Whiting Company Qualified Engineers Name: Damian Whiting