REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998.



NAD No apparent defect. SAR See attached report. NA Not available.		2leg 13mm 6mtr chain sling	2leg 13mm 6mtr chain sling	DESCRIPTION	DA12 2QD		J&M CRANES DENTON WHARF GRAVESEND		Name and address of customer:	
S.DARTNALL	Company approved examiner making this report: W.FOSKETT Name of person authenticating report Signature of person authenticating report	ling	ling							
ď	aminer making this re	EXAM	EXAM	DETAILS OF ANY TEST		DA	KENT	2 S		Addr
A	port:	YES	YES	SAFE TO USE?		DA1 1JD	2T	QUESTER, DARTFORD		Address at which the examination was made:
		CC70-2	CC70-1	SERIAL NUMBER / PLANT NUMBER				UNIT 20 APPLEGARTHE DRIVE QUESTER, DARTFORD		
Applicable for	Name and add HUDSON UNIT 71 THAN TILBURY, ESS	5.3T	5.3T	S.W.L						
Applicable for New Equipment	Name and address of company authentic HUDSON LIFTING LIMITED UNIT 71 THAMES INDUSTRIAL PARK, F TILBURY, ESSEX, RM18 8RH Original Manufacturer DofC held at Head	NAD	NAD	STATUS CODE	Exceptional Circumstances	12 Monthly	6 Monthly	Reason for examination: After installation / assembly	Date of report	Report number
	Name and address of company authenticating this report: HUDSON LIFTING LIMITED UNIT 71 THAMES INDUSTRIAL PARK, PRINCESS MARGARET ROAD, EAST TILBURY, ESSEX, RM18 8RH	10-7-25	10-7-25	DATE OF EXAMINATION						
velania Ca Veda		N/A	N/A	DATE OF LAST EXAMINATION (IF KNOWN)		<u></u>	×	STATUTORY	10-7-25	2252229
	OAD, EAST	9-1-26	9-1-26	LAST DATE BY WHICH NEXT EXAMINATION MUST BE CARRIED OUT				ΥY		